



Photo 1 – Supplied photo of the front of the airplane with its nose and right landing gear collapsed.



Photo 2 - Supplied photo of the right side of the airplane.



Photo 3 - Supplied photo of the instrument panel with the landing gear handle in the up position.



Photo 4 - Supplied photo of the airplane recovered to ramp parking.



Photo 5 - Supplied photo of the airplane cowling showing skin deformation around the nose landing gear.



Photo 6 - Supplied photo of the airplane fuselage showing skin deformation around the left main landing gear.



Photo 7 - Supplied photo of the airplane fuselage showing both main landing gear.



Photo 8 - Supplied photo of the engine mount showing displaced vibration isolation material.



Photo 9 - Supplied photo of the right elevator showing upper skin deformation,