



Photo 1 – Supplied view of the right side of the inverted airplane.



Photo 2 - Supplied quartering view of the right rear side of the inverted airplane.



Photo 3 - Supplied view of the left side of the inverted airplane. A tree is observed in a hole in the left wing.



Photo 4 - Supplied view of the front of the recovered airplane.



Photo 5 - Supplied view of the engine dataplate.



Photo 6 - Supplied view of removed sparkplugs.



Photo 7 - Supplied view the throttle linkage.



Photo 8 - Supplied view the mixture linkage.




Photo 9 - Supplied view the manifold valve.



Photo 10 - Supplied view the instrument panel.



Photo 11 - Supplied view the removed engine driven fuel pump and shear shaft. The shear shaft is intact.



11BPhoto 12 - Supplied view the fuel flow meter.



Photo 13 - Supplied view the gascolator assembly. The assembly exhibits blue stains.



Photo 14 - Supplied view the fuel filter.



Photo 15 - Supplied view the fuel servo filter.