



**Photo 1 – Skid marks in the grass depict where the helicopter touched down and slid (FAA photo)**



**Photo 2 - Ground furrows consistent with a hard landing (FAA photo)**



**Photo 3 - N153SA, a Bell OH-58A, at the accident site (FAA photo)**



**Photo 4 - Tail boom covering torn away, exposing severed tail rotor driveshaft (FAA photo)**



**Photo 5 – Impact Buckling on bottom of tail boom (FAA photo)**



**Photo 6 – Damaged main rotor blade tip (FAA photo)**



**Photo 7 – The cockpit (FAA photo)**