



**Vehicle Attachment – Vehicle Factors Photographs**

**Andrews, TX**

**HWY22MH006**

(5 pages)



**Photograph 1:** A view of the damage sustained at the front of the pickup



**Photograph 2:** A view of the damage sustained at the right front of the pickup





**Photograph 3:** A view of the damage sustained at the right rear of the pickup



**Photograph 4:** A view of the damage sustained at the left side of the pickup





**Photograph 5:** A view of the damage sustained at the right front of the van



**Photograph 6:** A view of the damage sustained at the right side of the passenger compartment of the van



**Photograph 7:** A view of the damage sustained to the right rear of the van



**Photograph 8:** A view of the damage sustained at the left rear of the van