




**Photo 1 – Main Wreckage (FAA Photo)**




**Photo 2 - Main Wreckage (FAA Photo)**



**Photo 3 - Empennage (FAA Photo)**



**Photo 4 – Engine Firewall Damage (FAA Photo)**



**Photo 5 – Throttle Cable/Fuel Injector Servo Linkage (FAA Photo)**



**Photo 6 – Fuel Control Attachment Hardware (FAA Photo)**