

## **Underwater Inspection Report**

Bridge Number	Route		Agency/Owner	Date					
50912 East 11th Street		City of Tacoma	25-Jan-13						
Bridge Name			· -	Intersecting					
Hylebos Waterway CS27	746			Hylebos Waterway					
Inspector			Identification No.	Hours on Site					
Matt Perry			G1217	13.3					
Dive Contractor			31217	10.0					
BergerABAM									
Diver Name			Diver Name	Diver Name					
Brett Ozolin, Scott Branlund			Matt Perry, Jeffrey Wilson						
Structure Type			Substructure Type						
Bascule			Concrete Bascule Foundation, Cocnrete Columns						
Foundation Type			Number of Spans Numbers of Piers in Waterway						
Concrete Piers and Columns			6	5					
Concrete 1 lets and Cold			U						
8 Bents 4-5 Concrete Columns/Shafts									
Abut/Pier Wall (2) Web Wall (3) Columns (4) Shaft (5)		All six columns and associated drilled shafts are in good condition. Level II cleanings were performed on two of the six, with no idication of damage.							
					Piles (6)		S		
					Bracing (7)		Concrete Piers		
7 Foundation (8) 8-9 Footing (9)		Both bascule foundations are in good condition. Small areas of poorly consolidated concrete and corner spalls were found in several locations.							
					Seal (10) Piles (11)			ust staining found throughou	
1 (1.1)		in the intertidal zor		at the structures, primarity					
8 Scour (12)	10	in the intertitual zone.							
Scour Mitigat. (13)	12	Scour/Scour Mitig	otion/Channal						
8 Channel (14) Steambed (15)	14-17	Scour/Scour Mitigation/Channel The sandy substrate around the bottom of each pier shows little signs of scour. The northwest corner of the east bascule foundation has some of the top of the footing exposed. Due to the thickness of the footing, scour							
Drift (16)									
Flow (17)		was not rated as a		diess of the footing, scoul					
		was not rated as a c	concern.						
<del></del>		Channel							
			The channel is well protected and appears to be stable.						
		The channel is wen protected and appears to be stable.							
<del></del>									
<del></del>									