
## Jacqueline A - Additional Photos



Doubler plates, port bow



Doubler plates, starboard bow




Doubler plate, starboard aft



Wastage, port deckhouse



Bilge high water float sensor, engine room forward



Wire run opening, aft engine room bulkhead (foam added during salvage post-sinking)



Gasked, port lazarette hatch