



Motor Carrier Attachment –AMT Security Camera Video Review

Phoenix, AZ

HWY21MH008

(11 pages)

Disclaimer: All times reflected in the following photo titles do not match video camera still image due to camera recording device not in sync with accurate time. For additional information, see *NTSB Vehicle Recorder Division Security Video - Time Correlation Report* in the Docket.



Figure 1. 06/06/2021, 11:17:13 - Driver in POV arrives at office.



Figure 2. 06/07/2021 00:45:13 - Driver outside office, about to enter.



Figure 3. 06/07/2021, 01:16:25 - Driver leaving office.



Figure 4. 06/07/2021, 01:16:31 - Driver leaving office.



Figure 5. 06/07/2021, 13:08:56 - Driver parks POV near truck, checks out truck, then drives POV to parking spot.



Figure 6. 06/07/2021, 13:18:38 - Driver's POV passing office door on way to parking spot.



Figure 7. 06/07/2021, 13:21:10 - after parking POV, driver returns to truck and drives away.



Figure 8. 06/08/2021, 03:02:08 - Driver returns to office.



Figure 9. 06/08/2021, 03:02:20 - Driver enters office.



Figure 10. 06/08/2021, 03:07:48 - Driver leaves office.



Figure 11. 06/08/2021, 13:56:16 - Driver in office.



Figure 12. 06/08/2021, 14:03:55 - driver leaving office.



Figure 13. 06/09/2021, 04:24:16 - driver returns to office.



Figure 14. 06/09/2021, 04:24:35 - Driver enters office.



Figure 15. 06/09/2021, 14:16:43 - Driver POV parked next to truck, checked out truck, went to park POV.



Figure 16. 06/09/2021, 14:25:34 - Driver POV seen on door camera, heading to park POV.



Figure 17. 06/09/2021, 14:29:15 - after parking POV, driver returns to truck and departs. Last sighting before accident.



Figure 18. 06/10/2021. 13:01:07 - driver returns after accident.



Figure 19. 06/10/2021, 14:29:14 - driver leaving in POV after accident.