# **BNSF Railway**

## **BNSF Inspection Report - Switch Tests & Inspections**

Inspection #: 001013258193 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division:PRAsset ID:BAEFBXESubdivision:PIKES PEAKTest Date:2023-10-11

**Line Segment / Milepost:** 0477 ~ 109.67 - 109.67 **State:** CO

Location / Highway Name: S. BRAGDON

County: PUEBLO

Employee's Name: PI

Switch Type: POWER-OP

#### Gang ID: PII

#### **Conditions Master Key**

Tested OK = Test completed, no exceptions found, and condition left in compliance

 $Adjusted/Tested\ OK=Adjustments\ made\ (identified\ in\ associated\ comments),\ test\ completed,\ and\ condition\ left\ in\ compliance$ 

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance

### **Operations Without Measurements**

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)	NOT APPLICABLE	B002112
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	B002112
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	B002112
PT. DET./CC - NORMAL (FRA-236.103).  ADJUSTED TO INDICATE ON 1/8 AND NOT INDICATE ON 1/4	ADJUSTED/TESTED OK	B002112
PT. DET./CC - REVERSE (FRA-236.103).  ADJUSTED TO INDICATE ON 1/8 AND NOT INDICATE ON 1/4	ADJUSTED/TESTED OK	B002112
SHUNT FOULING (FRA-236.104)	TESTED OK	B002112