

ANC23FA031

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Video frame seconds before impact with terrain from attached Go-Pro camera on helicopter.**





**Photograph 2 - Video frame from attached Go-Pro camera. Fragments of the main rotor blades can be seen at the top of the frame.**



**Photograph 3 - Main rotor blade tip damage (Courtesy of NTSB)**





**Photograph 4 - Aerial view of accident site. (Courtesy of Sheriff's Department)**