

ANC23LA060

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Damage to the left wing of the accident airplane at the recovery site.**



**Photograph 2 - Right side of accident airplane at recovery site.**





**Photograph 3 - Damage to the left wing of accident airplane at recovery site.**