

ANC23LA067

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of fuselage and right wing after recovery (Courtesy of Operator)



Photograph 2 - View of right side wing root (Courtesy of Operator)



Photograph 3 - View of the airplane in the water where it came to rest. (Courtesy of Operator)