



Photo 1 – View of nosed over amphibious float plane in a lake with extended landing gears (courtesy of the FAA)



Photo 2 - View of damaged engine truss (courtesy of the FAA)