



Photo 1 – View of damaged engine truss (courtesy of the FAA)