



Photo 1 – View of damage to right wing and lift strut (courtesy of the pilot)