



**Photo 1 – Right side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).**



**Photo 2 – Front view of the airplane at the accident site (courtesy of the Federal Aviation Administration).**



**Photo 3 – Left side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).**



**Photo 4 – Close up left side view of the collapsed nose landing gear at the accident site (courtesy of the Federal Aviation Administration).**



**Photo 5 – Close up view of the fracture sustained to the upper portion of the engine mount (courtesy of the Federal Aviation Administration).**



**Photo 6 – Close up view of the fracture sustained to the upper portion of the engine mount (courtesy of the Federal Aviation Administration).**



**Photo 7 – Close up view of the fracture sustained to the lower portion of the engine mount (courtesy of the Federal Aviation Administration).**



**Photo 8 – Close up view of the fracture sustained to the lower portion of the engine mount (courtesy of the Federal Aviation Administration).**