



**Photo 1 – Damage to Inboard Left Wing Leading Edge (Courtesy of Operator)**