



Photo 1 – View of the front of the airplane at the accident site (courtesy of Textron Aviation).



Photo 2 – View of the left side of the airplane at the accident site (courtesy of Textron Aviation).



Photo 3 – View of the rear of the airplane at the accident site (courtesy of Textron Aviation).



Photo 4 – View of the right side of the airplane at the accident site (courtesy of Textron Aviation).



Photo 5 – View of the fuel selector in the cockpit (courtesy of Textron Aviation).



Photo 6 – View of the fuel selector removed from the airplane (courtesy of Textron Aviation).



Photo 7 – View of the total amount of fuel obtained from the fuel selector (courtesy of Textron Aviation).



Photo 8 – View of the right side of the engine at the accident site (courtesy of Textron Aviation).



Photo 9 – View of a propeller blade, on the left side of the airplane, at the accident site (courtesy of Textron Aviation).



Photo 10 – View of a propeller blade, on the right side of the airplane, at the accident site (courtesy of Textron Aviation).



Photo 11 – View of the cockpit area (courtesy of Textron Aviation).



Photo 12 – View of the engine compartment, with a screwdriver plugging a rubber hose (courtesy of Textron Aviation).