



**Photo 1 – Front view of the airplane at the accident site.**





**Photo 2 – Left side view of the airplane at the accident site.**





**Photo 3 – Rear view of the airplane at the accident site.**





**Photo 4 – Right side view of the airplane at the accident site.**





**Photo 5 – Close up view of the front of the airplane at the accident site.**





**Photo 6 – View of the wreckage laid out after it was recovered from the accident site.**






**Photo 7 – View of the empennage, showing the dorsal fin.**





**Photo 8 – View of the right side of the engine during the examination.**





**Photo 9 – View of the front of the engine during the examination.**





**Photo 10 – View of the left side of the engine during the examination.**





**Photo 11 – View of the propeller removed from the engine.**





**Photo 12 – View of an exemplar propeller installed on the engine during the examination.**