

CEN23LA107

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident site (Courtesy of the Federal Aviation Administration)



Photograph 2 - View of the accident site (Courtesy of the Federal Aviation Administration)



Photograph 3 - View of the front of the airplane at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 4 - View of the left wing at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 5 - View of the left side of the airplane at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 6 - View of the right side of the airplane at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 7 - View of the right wing at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 8 - View of the underside of the fuselage at the accident site, coated with engine oil (Courtesy of the Federal Aviation Administration)



Photograph 10 - View of the cockpit at the accident site (Courtesy of the Federal Aviation Administration)



Photograph 11 - View of the front of the airplane at the salvage facility



Photograph 12 - View of the right side of the airplane at the salvage facility



Photograph 13 - View of the left side of the airplane at the salvage facility



Photograph 14 - View of the empennage at the salvage facility



Photograph 15 - View of both wings at the salvage facility



Photograph 16 - View of the right side of the engine at the salvage facility



Photograph 17 - View of the left side of the engine at the salvage facility



Photograph 18 - View of the underside of the fuselage at the salvage facility, coated with engine oil



Photograph 19 - View of the spark plugs at the salvage facility



Photograph 20 - View of the Hobbs meter at the salvage facility