



**Photo 1 – View of nosed over airplane (photo courtesy of the pilot)**



**Photo 2 – View of damaged right-wing lift strut (photo courtesy of the pilot)**



**Photo 3 – View of damaged empennage (photo courtesy of the pilot)**