

WPR19LA006 Accident Pictures:



Figure 1: Ground impression leading to airplane wreckage (inverted).



Figure 2: Ground disturbance with separated forward section of spinner located in it.