



Photo 1 – Left aft view of airplane in the trees and brush. (Courtesy of FAA)



Photo 2 – Aft view looking forward. Note crumpled wings and flaps. (Courtesy of FAA)



Photo 3 – Left wing leading edge and strut damage. (Courtesy of FAA)



Photo 4 – Right wing leading edge damage. (Courtesy of FAA)



Photo 5 – Overall view of airplane damage after recovery to hanger. (Courtesy of Richmor Maintenance)



Photo 6 – Left aft quarter view of airplane damage after recovery to hangar. (Courtesy of Richmor Maintenance)



Photo 7 – View of trees and brush adjacent to runway 21, where the airplane entered. (Courtesy of Richmor Maintenance)