

ERA24LA011

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft view of airplane damage. (Courtesy of FAA)



Photograph 2 - Forward view of airplane damage. Note both wings broken downwards. (Courtesy of FAA)



Photograph 3 - Right profile view of airplane damage. (Courtesy of FAA)



Photograph 4 - Initial ground impact site. (Courtesy of FAA)



Photograph 5 - Close up view of propeller and engine compartment. (Courtesy of FAA)