

[ERA23LA334]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of airplane showing damage. (Courtesy of FAA)



Photograph 2 - View of thermal damage to engine cowling. (Courtesy of FAA)



Photograph 3 - Electrical arcing damage to wing strut. (Courtesy of FAA)



Photograph 4 - View of airplane during recovery, right side damage (Courtesy of FAA)