

Additional Post-Explosion Site Photographs



Figure 1. Indicator on Mainline Valve (6/28/2021 at 7:04PM, Courtesy of RRC)



Figure 2. Flare System (6/28/2021 at 7:05PM, Courtesy of RRC)



Figure 3. Grounding Cable (6/29/2021 at 1:10PM, Courtesy of RRC)



Figure 4. Launcher door (6/29/2021 at 1:17PM, Courtesy of RRC)



Figure 5. Ignitor – Front View (7/2/2021 at 3:39PM)



Figure 6. Ignitor - Side View (7/2/21 at 3:43PM)