



Appendix S to the Water Treatment Plant Factual Report, Photo 10, Excavating to remove second pipe segment containing anomaly.