



Appendix S to the Water Treatment Plant Factual Report, Photo 13, View of external damage to second pipe segment.