



Appendix S to the Water Treatment Plant Factual Report, Photo 14, Internal view of damage to second pipe segment.