



Appendix S to the Water Treatment Plant Factual Report, Photo 2, Beginning excavation to recover ruptured pipe.