



Appendix S to the Water Treatment Plant Factual Report, Photo 4, Exposing rupture in relation to waterline tee and PVC utility duct crossing.