



Appendix S to the Water Treatment Plant Factual Report, Photo 7, Internal view of damage to ruptured pipe segment.