




FACTUAL REPORT OF INVESTIGATION ATTACHMENT

Sunnyvale Inspection Photographs

West Hollywood, CA

HWY18FH014

(10 pages)



Sunnyvale Inspection Photo 1: view showing Tesla motor



Sunnyvale Inspection Photo 2: view showing the battery pack label



Sunnyvale Inspection Photo 3: view showing underside of Tesla battery pack



Sunnyvale Inspection Photo 4: view showing underside left front corner of battery pack



Sunnyvale Photo 5: view showing detail of the underside of the battery pack



Sunnyvale Inspection Photo 6: view showing the upper left front of the battery pack at beginning stage of cover removal



Sunnyvale Inspection Photo 7: view showing the upper side of battery pack with covers removed



Sunnyvale Inspection Photo 8: view showing the front of the battery pack with some modules and components removed



Sunnyvale Inspection Photo 9: view showing a detailed view of the front center of the battery pack with front modules removed



Sunnyvale Inspection Photo 10: view showing the left front of the battery pack with some components removed



Sunnyvale Inspection Photo 11: detail view of the left front of the battery pack



Sunnyvale Inspection Photo 12: detail view of damage to the left front battery case



Sunnyvale Inspection Photo 13: detail view of damage to the left front battery case



Sunnyvale Inspection Photo 14: view of left front battery case



Sunnyvale Inspection Photo 15: detail view of the damage to battery case



Sunnyvale Inspection Photo 16: detail view of damage to battery case