



NY DEP Sewer video
Pre-accident inspection
October 16, 2006




NY DEP Sewer video
Pre-accident inspection
August 24, 2011



NY DEP Sewer video
Post-accident inspection
March 19, 2014

Camera inspection of the
sewer was performed after
the accident



NY DEP Sewer video
Post-accident inspection
March 28, 2014

Flourescent dye was introduced
at the location of the gas pipe
failure and observed flowing
into the sewer