



## Dynamic Access System for HIQA

## CAR Details

**Permittee:** 00100 - CONSOLIDATED EDISON  
**CAR Number:** 20125280371 **CAR Status:** Closed / Repaired **CAR Date:** 10/13/2012  
**Permit Number:** M012011362128 **Approved By:** Alonzo Jones **Approval Date/Status:** 10/16/2012 / Approved  
**Print/Email Date:** 10/17/2012 **Inspection Reason:** Post-Audit **Inspected By:** 528 - Nathaniel Walls

<b>Lane Of Cut:</b>	<b>Parking</b>	<b>Traffic Flow:</b>	<b>Heavy</b>	<b>SR Number:</b>	<b>N/A</b>
<b>Feet From X Street:</b>	<b>0</b>	<b>X Street Name:</b>	<b>N/A</b>	<b>Feet From Curb:</b>	<b>0</b>
<b>Priority:</b>	<b>No</b>	<b>Protected:</b>	<b>No</b>		
<b>CAR Comments:</b>	<b>Perm. gas trench needs to be resealed.</b>				

## Defects

**Defect Code:** 72 - Not Sealed **Number of Cuts:** 1 **Depth Of Cut (inches):** 0

NOVNumber	NOV Date	NOV Code	Code Section	NOV Description	Details of Violation	Place of Occurance	Inspector
181870857	1/19/2013	D5A	34RCNY 2-11(e) (12)(viii)	Failure to seal street opening joints	Respondent failed to reseal permanent trench.	1642 Park Ave	455 - Doreen Rose

Welcome Grace Aitcheson [ You are logged with the following roles: Guest ]



# Dynamic Access System for HIQA (/DASHOffice/)

Permits

CAR

Inspections

**Inspections Search**Permit Number: Borough: Inspection Date From: Inspection Type: Permittee: Inspection Date To: Inspection Result: Inspector: Siebel Number: NOV Number: 

Search

Clear

Total Record Count: 7

Page(s): 1

Current Page: 1

Inspection Date	Permit Number	Permittee	Permittee Name	Reason	Result	Sector	Inspector	SR Number	NOV Number	House Number	On Street	From Street	To Street
9/25/2013 7:18:16 AM	M012011362128	00100	CONSOLIDATED EDISON	Post-Audit	Pass	066	455 - Doreen Rose			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks:</i>													
3/23/2013 11:17:30 AM	M012011362128	00100	CONSOLIDATED EDISON	CAR Re-Inspect	Pass	066	441 - Sydney Marshall			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks: restoration trench has been resealed.</i>													
1/19/2013 8:32:21 AM	M012011362128	00100	CONSOLIDATED EDISON	CAR Re-Inspect	NOV (Other)	066	455 - Doreen Rose		181870857	1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks: Respondent failed to reseal permanent trench.</i>													
10/13/2012 3:20:22 PM	M012011362128	00100	CONSOLIDATED EDISON	Post-Audit	CAR (Other)	066	528 - Nathaniel Walls			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks: Perm. gas trench needs to be resealed.</i>													
1/13/2012 11:53:49 AM	M012011362128	00100	CONSOLIDATED EDISON	Active	Pass	066	441 - Sydney Marshall			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks:</i>													
1/11/2012 12:00:00 AM	M012011362128	00100	CONSOLIDATED EDISON	Active	Pass	066	138 - Gregory Shirley			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks: Okay.</i>													
12/28/2011 12:00:00 AM	M012011362128	00100	CONSOLIDATED EDISON	Active	Pass	066	403 - Douglas Lynch			1642	PARK AVENUE	EAST 116 STREET	EAST 117 STREET
<i>Inspection Remarks:</i>													