evel ( ^dad (■ FIPELINE ROBOTICS Getting Out & (\*) Staying Out The Kiosk (Y) AmerZafrica WHW NA (A) O 95 Park Deli (41) Iglesia Cristiana 👜 Absolute Piano 🟝 INCIDENT GRNRF(\*) Park Ave Q Customer Name: Date of Inspection: Urban Garden Center (🕏 Park Ave \_ ~50′ March 19, 2014 Con Edison Company of New York Park Ave Parks



Town: Manhattan, NY

Project: Gas	Main Inspection	Pipe Size:	8" Cast Iron, Inert		
Address of Pit Location 116	th St & Park Ave South	Date:	3/19/2014		

of Pit Location 116th St & Park Ave South Date: 3/19/2014

Project Pit #: 2 Completed By: Steven Mckeefrey

Direction: North Crew: Steven Mckeefrey, Jerry Taverna

Inspector: Anthony Mancino Equipment: Small VGC

## Con Edison

Distance (Feet)	Notes	Comments
0	Enter Main heading North	
10	Joint	
22	Joint	
36	Joint	
41	Joint	
43	2" plug .	
44	2" plug	
45	Transition Cast Iron to Plastic (PE)	
48	Butt weld on plastic (PE) main	
50	Cross weld	
51.5	6" Tee	at 3:00 O'clock
51	Cross weld	
52	6" Tee	at 9:00 O'clock
52.5	Butt weld	
58.5	2" tapping tee	
59	2" tapping tee	
59	Butt weld	
59.5	Butt weld	
60.5	Butt weld	
62	2" tapping tee	
63	Butt weld	
83	Butt weld	
102	Butt weld	
110.2	2" Service	Possibly disconnected from the main Tracer wire visible
115	Start of water in main	
118	Debris not allowing small VGC to move forward	End of Inspection
100		



## **Inspection Map**

**Project:** Gas Main Inspection

Address of Pit Location 116th St & Park Ave South

Project Pit #: 2

Direction: North

Inspector: Anthony Mancino

**Date:** 3/19/2014

Completed By: Steven Mckeefrey

Crew: Steven Mckeefrey, Jerry Taverna

**Equipment:** Small VGC

_	Footage from Pit	PITE	0	10	22	36	41	43	44	45	48
	Notes	116th St & Park Ave South	· Enter Main heading North	Joint	Joint	Joint	Joint	2" plug	2" plug	Transition Cast Iron to Plastic (PE)	Butt weld on plastic (PE) main
	Comments	Wajn Location	0	0	0	0	. 0	0	0	0	0

i i																		
50	51.5	51	52	52.5	58.5 ,£	59 -	59	59.5	60.5	62	63	83	102	110.2	115	118	0	0
Cross weld	6"Tee	Cross weld	6"Tee	Butt weld	2" tapping tee	2" tapping tee	Butt weld	Butt weld	Butt weld	2" tapping tee	. Butt weld	Butt weld	Butt weld	2" Service	Start of water in main	Debris not allowing small VGC to move forward	0	0
0	at 3:00 O'clock	0	at 9:00 O'clock	0	0	0	0	0	0	0	0	0	0	Possibly disconnected from the main⊡Tracer wire visible	0	End of Inspection	0	0