

Attachment 35

NYCDEP Exploratory excavations on Park Avenue



Figure 1: Excavation for the sewer connection at 1642 Park Avenue revealed presence of boulders in the backfill materials. Source: NYCDEP



Figure 2: Excavation for the sewer connection at 1642 Park Avenue continued to show boulders in backfill materials being split with drill. Sources NYCDEP.





Figure 3: Direct Connection of 1642 Park Avenue lateral into the combined Sewer Main without “a riser”. Source: NYCDEP



Figure 4: Close north side view of direct connection of 1642 Park Avenue Sewer lateral into the combined Sewer Main without “a riser”. Source: NYCDEP



Figure 5: Close top view of direct connection of 1642 Park Avenue Sewer lateral into the combined Sewer Main without “a riser”. Source: NYCDEP