



## **Highway Factors Photographs**

**Belton, South Carolina**

**HWY20FH001**

(10 pages)



Highway Photo 1- This photo shows US-76 looking east the direction the SUV was traveling when it crossed over into the opposing traffic lane at the curve in the background.



Highway Photo 2 – Closer view of SUV driver’s approach to the curve where the crash occurred.



Highway Photo 3 – Eastbound view of the curve alignment on US-76 with the impact area in the westbound lane.



Highway Photo 4 – View of US-76, looking east in the westbound lane, showing the darkened pavement area where the impact occurred.



Highway Photo 5 – View from US-76 centerline double yellow pavement stripe, showing the impact marks in the westbound lane with SUV’s departure tiremarks leading back across the eastbound lanes onto the south roadside.



Highway Photo 6 – Westbound view of the curve on US-76 where the crash occurred. A vehicle is seen in the photo entering the curve so the reader can see the roadway alignment.



Highway Photo 7 – Westbound view of the curve where the crash occurred with an approaching SUV in the eastbound lane.





Highway Photo 8 – Closer view of curve alignment from the westbound lane.



Highway Photo 9 – Close-up view of impact area in the westbound lane where the SUV crossed into the opposing traffic lane. Gouges and tiremarks on the pavement show where the vehicles collided head-on.