

ANC15FA032- Wreckage diagrams

The Safety Board investigator-in-charge performed an on scene wreckage documentation and initial examination on June 1, 2015. The main fuselage was located at 60.332588N -161.054495W, about 270 feet from the first observed point of impact, on a magnetic heading of approximately 010 degrees.



Figure 1: Illustrated aerial picture of the wreckage site



Figure 2: Broken trees looking back in the direction of flight path



Figure 3: Initial ground impact point



Figure 4: Looking back at the flight path from the main fuselage



Figure 5: Propeller tip sticking out of the water