



# Bellingham, Washington June 10, 1999

# **Pipeline Rupture and Subsequent Fire In Bellingham, Washington**



# **Bellingham, WA**






## **Bellingham, WA**







#### Whatcom Creek



#### West End of Burn

#### Interstate 5

#### Aerial View from WDOE National Transportation Safety Board

#### **Rupture Site**

Water Tanks


#### Burned

### **Area Along**

#### **Whatcom Creek**








#### **External Gouges on Ruptured Pipeline**






#### **Close-up View of Gouge at Origin**







#### **Bayview Products Terminal**

1.010



#### **IMCO's excavations in the vicinity**

## of Olympic's pipeline.



# **Olympic's evaluation of the results**

### of in-line inspection data.



#### **Olympic's management**

#### of the construction and commissioning

## of the Bayview Products Terminal.



# The performance and security of Olympic's SCADA system.



# Federal regulations regarding the testing of relief valves.



### **Parties to the Investigation:**

**RSPA's Office of Pipeline Safety Olympic Pipe Line Company IMCO** General Construction, Inc. **Fisher-Rosemount Petroleum Earth Tech City of Bellingham** Washington State Department of Ecology **Washington State Fire Marshal US Environmental Protection Agency** 



**Investigation Team:** John Hammerschmidt - Member Allan Beshore – Investigator-in-Charge **Cliff Zimmerman – In-Line Inspections Leslee Shumway – SCADA** Jim Cash – SCADA Frank Zakar – Metallurgy **Bob Trainor – Relief Valve** Jim Gildea – Survival Factors Joe Kris – Survival Factors **Dr. Steve Jenner – Human Performance Tom Lasseigne – Environmental Response Robert Moore – Report Writer and Editor Keith Holloway – Public Affairs** 





