



**Serving Louisiana and Texas**

P. O. Box 1408  
Groves, TX 77619  
(409)962-2034  
(866)962-2034

---

**L M BOTRUC  
BOTRUC 33 INSPECTION**

On 10/11/2020 Diver Dan Diving Service conducted an inspection of crewboat Botruc 33. Diver inspected starboard prop/rudder, no problems. Mid prop has 1" cable wrapped around. Port prop has 1" cable in flukes as well. Diver was unable to inspect mid ship due to depth of water. Roughly 2 feet of clearance between hull and bottom. Same goes for bow. Diver cut out all cable (60 feet) from both shafts. Boat captain moved boat forward to gain more clearance under boat. Diver was able to complete inspection finding no damage along hull of the boat.

**Dive Supervisor: Nathan Raggio**