



Bridge Factors Photographs – MCM’s Photo Submission

Miami, FL

HWY18MH009

(9 pages)

September 1, 2017

1:18:58 AM

The first attempt to pour the deck with concrete was aborted because of a plant malfunction, all concrete was removed and the formwork, ducts and rebar were cleaned and/or replaced in the poured part.



September 1, 2017
1:23:01 PM

The first attempt to pour the deck with concrete was aborted because of a plant malfunction, all concrete was removed and the formwork, ducts and rebar were cleaned and/or replaced in the poured part.



March 10, 2018
Time: Unknown

View along west side of Diaphragm II looking to the east.



March 10, 2018

Time: Unknown

View of bottom of diagonal support #11 on east side looking to the west.

