



Photo 1 – Damage to Right Main Landing Gear Strut



Photo 2 – Damage to Right Aileron