



Photo 1 – Damage to the Nosewheel and Lower Fuselage



Photo 2 – Damage to Interior Floorboards on Passenger Side