

Date	O&M and IM Project Description	Project Details
July, 2019	Surficial Earth Moving to Address Topsoil Erosion	Surface earth moving to address top erosion downhill from the Failure Location. There was some earth work to reshape the topsoil to the east of the lines and extending over Lines 15 and 25. This location is approximately 250-ft from the Failure location over Line 25.
February 7, 2019	Anode Bed Due to CIS Lows	A deep well anode bed was installed at MP 510 due to low potentials measured during a Close Interval Survey (CIS) that occurred on 8/23/2018, the CIS revealed low potentials from MP X to MP X (66ft) and MP X to MP X (99ft)
February 8, 2019	Anomaly Investigation	Following anomaly investigation, 8 ft of recoat was performed on Line 15 from WC 41270.840 to WC 41281.340
February 9, 2019	Assessments - Caliper and IMU	Performed Caliper and IMU tool run
April 17, 2018	Assessments - Caliper , IMU and MFL-A	Performed Caliper, IMU and MFL-A tool run