

July 1, 2021

Original, as-built depth-of-cover for Lines 10, 15, and 25 at the location nearest to the failure location

At this time, TETLP has not been able to locate the original as-built depth of cover in our records.