



Photo 1 – View of left wing damage (photo courtesy of local law enforcement)



Photo 2 - View of vertical stabilizer and rudder damage (photo courtesy of local law enforcement)



Photo 3 - View of right wing and lift strut damage (photo courtesy of local law enforcement)