



Photo 1 – View of the right-wing lift strut damage (photo courtesy of the pilot)



Photo 2 - View of the vertical stabilizer and rudder damage (photo courtesy of the pilot)