



5-2-23

PO# 0088373

Invoice # 2023006

Dive report for the Cedarville dock on 5-2-2023.

I arrived at the dock at the agreed upon time and held a safety briefing. I entered the water where the dock personnel thought that the problem area might be. I began my dive towards the south. I did not see any visible damage to the dock anywhere. I did not find any large boulders or places where the bedrock was sticking up. I did find a berm of sand and gravel near the south end of the dock. This berm was approximately 6 to 8 feet from the dock and was approximately 4 feet high. It ran the last 50 feet of the dock. This appears to have been caused by vessels using their bow thrusters. I took pictures of the berm and also pictures of the depth on the top of the berm. I also noted some bedrock at the south end of the dock. None of the bedrock appeared to have been disturbed recently. I also found a trench on the bottom that was approximately 6 to 8 feet wide. I took pictures of all of the above and returned to the entry point.

I agreed to complete the dock survey to the north as I had plenty of air and was not feeling the cold. I did not see any visible damage to the dock anywhere. I did find some bedrock shoals near the loader and near the north end of the dock. I took pictures of the shoals and ended my dive.

This concludes the report.

Robert Doyle

Robert Doyle  
Dive Instructor

