



Photo 1 – View of Airplane as Found (FAA)



Photo 2 - View of Fractured Engine Mounts and Fuselage Damage (FAA)



Photo 3 - View of Adapter Fitting as Installed (Owner)



Photo 4 - View of Disconnected Adapter Fitting (FAA)



Photo 5 - View of Owner's Modified Spanner Wrench (FAA)